

Weddle Tool Company Inc. – 877-79W-TOOL – www.weddletoolco.com

Fan Hanger Installation

- Remove Shoulder Strap from the W Tool
- Place the Fan Hanger Assembly on the top of the main body of the W Tool and align the attachment slots in the Fan Hanger Assembly over the "Right" and "Left" shoulder strap attachment points on the tool.
- After correct placement of the fan hanger assembly on the W Tool secure the assembly safety snaps to the W Tool shoulder carry anchor points on the tool.
- Secure the Velcro closure on the bottom of the W Tool.
- The Fan Adjustment Straps should always hang from the "TOP" of the W Tool.



Fan Hanger Hardware Installation

- 1 Set of Fan Hanger Hardware is included with each Fan Hanger Kit
- Secure the attachment hardware to the top of the ventilation fan as follows:
 - o Hardware should be attached to the top outside corners of the fan.
 - o Hold the hardware in place on the fan and mark each hole.
 - o Drill a 3/16" hole at the four marked placements on the fan.
 - o Secure the attachment D Ring with the provided 3/16' pan head bolt and 3/16" nylon lock nut.
 - o D Rings should be attached flush with the top of the fan when in the folded down position.

